



Z





NORTH RETAINING WALL BETWEEN ABUTMENT 1 AND 2 - ELEVATION





ABUTMENT 1 - ELEVATION (Looking West)

SOUTH RETAINING WALL BETWEEN
ABUTMENT 1 AND 2 - ELEVATION

REVISIONS

LEGEND

Formed Concrete Repair (Depth =< 5")

BILL OF MATERIAL

ITEM UNIT TOTAL

Epoxy Crack Sealing FOOT 44

Formed Concrete Repair (Depth =< 5") SQ FT 170

TTTTA

Hair Line Crack

Epoxy Crack Sealing

S.N. 016-0143 SCALE: N.T.S. DATE: MARCH 1, 2006 DESIGNED BY: MAF, DJR
DRAWN BY: MAF, DJR
CHECKED BY: MI

ILLINOIS DEPARTMENT OF TRANSPORTATION

SHEET 4 OF 12

TYLININTERNATIONAL

F.A.I. 94 (DAN RYAN EXPRESSWAY)

SUBSTRUCTURE REPAIR FOR BELT RAILWAY
EXISTING ABUTMENT 1